

MTS 6516

Version 2.3.170.8

Release Notes

December 7, 2021



BOSCH

Table of Contents

1. Purpose.....	4
2. Deliverables	5
3. Product Version Information.....	6
4. Summary of Resolved Issues.....	7
5. Test Plan and Results	8
6. Known anomalies	8



Revision History:

Version	Date	Description of Change
Draft	12/7/2021	- v2.3.170.8
		-



1. Purpose

The purpose of this document is to:

- a) Identify the list of Deliverables contained in this delivery;
- b) Identify the list of Jira tickets that have been addressed in the MTS 6516 delivery;
- c) Describe how this software delivery was tested and document the location of the test results; and
- d) Describe functional errata identified during internal testing of this firmware.

The following Product Type(s) are supported in this delivery:

- F-00K-108-824 - Kit, MTS 6516 VCI (no Wi-Fi)
- F-00K-108-867 - Kit, MTS 6516 with P2P Wi-Fi
- F-00K-108-999 - Kit, MTS 6516 with Wi-Fi



2. Deliverables

Item	Name:	Description:
2	setup.exe	MTS 6516 v2.3.170.8
3	Bosch MTS 6516 v2.3.170.8 Release Notes.pdf	MTS 6516 Release Notes



3. Product Version Information

Description	Version	Date
VCI Manager	2.3.170.8	vci-manager.exe
VCI Identification Service	2.3.170.8	vci-ident.exe
PDU-API Interface	2.3.170.8	BVTX-VCI-PDU.dll
J2534 API	2.3.170.8	BVTX4J32.dll
J2534 Configuration Application	2.3.170.8	J2534ConfigApp.exe
Vetronix Runtime API (v2.3)	2.3.170.8	BVTX-VCI-RT.dll
J2534 API Monitor	2.3.170.8	J2534Monitor.dll
PDU API Monitor	2.3.170.8	PDUMonitor.dll



4. Summary of Resolved Issues

Issue #	Description
GVCI-10643	6516 : Add support for 1 Mbps



5. Test Plan and Results

The MTS 6516 v2.3.170.8 was tested on Windows 10. The test results are archived in Jira and the Bosch Document Management system.

6. Known anomalies

Issue #	Description
None	There are no known anomalies

